CHEVAL RIANT
FIELD REPORT
CLIENT ◦ ANTOBOT
REF: ANTOBOT/GL181EB/0666

18:00
25.07.2026
51.941253, -2.396896

URGENT

51.940776, -2.399675

SECTION B ◦ SOUTH WEST
HAYGROVE WJQ3+74
Newent GL18 1EB

Terrain too rough for safe operation; trenches 10cm+ depth in some places. Suggest leave this section and nofity your client for clean up. 0011 and 0027 lose one month of life going here.

Media: https://chevalriant.com/antobot-gl181eb-0666/

N.B. Journey from station to tunnels still a rough ride - section of unpaved road between station and tunnels.

Garry Rigby [CHEVAL RIANT]

CHEVAL RIANT
Garry Rigby
+44 7880 821 227
garry@chevalriant.com

ANTOBOT
Ella Cormack
+44 7851 823 877
ella.cormack@antobot.ai